



NOTE: In the event of removing the turntable motor cover this part should be refitted using screw connection : **50282957005** (7-10)